


PRESSURE MAPPING, FORCE MEASUREMENT, AND TACTILE SENSORS



General Dimensions			Sensing Region Dimensions						Summary			
Overall Length <i>L</i>	Overall Width <i>W</i>	Tab Length <i>A</i>	Matrix Width <i>MW</i>	Matrix Height <i>MH</i>	Columns			Rows			Total No. of Sensels	Sensel Spatial Resolution
					<i>CW</i>	Pitch <i>CS</i>	<i>Qty.</i>	<i>RW</i>	Pitch <i>RS</i>	<i>Qty.</i>		
(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)		(mm)	(mm)			(sensel per sq-cm)
542.3	1484.6	228.6	1463.0	447.0	3.2	5.1	288	3.2	5.1	88	25,344	3.9
(in)	(in)	(in)	(in)	(in)	(in)	(in)		(in)	(in)			(sensel per sq-in)
21.35	58.45	9.00	57.60	17.60	0.125	0.200	288	0.125	0.200	88	25,344	25.0

Pressure Ranges

kPa	862
psi	125